

Fig. 1

Fig. 2




FIG. 3A





FIG. 3B






Fig. 4 A

ISDN PRI MODEM

400

Fig. 4B




FIG. 5A




FIG. 5B

ASSOCIATION				SLC	
CLIENT		SERVER			
IP ADDR.	Port	IP ADDR.	Port		
IPA	p1	IPB	pw	a	
IPA	p2	IPB	pw	b	

FIG. 5C




FIG. 6A




FIG. 6B




Fig. 7




FIG. 8




Fig. 9




Fig. 10




FIG. 11




Fig. 12




FIG. 13




FIG. 14

[DANTU ET AL.] [B5-0027]

17/17

